



Correct area, component, and procedure.

Look the job over and determine whether you are working in the right area, the right component, and using the right procedure.

azard and condition review.

Perform a review of the job hazards or any other condition that may be unsafe or interfere with safe performance of the task.

Evaluate for error traps.

Pre-determine possible error traps. Identify unsafe conditions.

Check for proper use of PPE.

Is the PPE adequate? Is PPE being worn correctly?

Keep attention on task.

Do not lose focus. Do not stop the job until it is completed.

